Idaho PUC Pipeline Safety Inspection Summary

nspector(s): Ulmer/Perkins/Russo			Date(s):	Feb 11-14, 2019
ompany/Owner: Avista Utilities		Unit/OPID:	31232	
Company/Owner:	AV	ista Utilities	Unit/OPID.	21727
Inspection Type & Time (1	day 0.5 day)	Total In	spection Days:	10
mspection type & time (=	ddy, o.o ddy,			
Standard: Construction:	Training: 10	(T)(D) Integrity Management:	Incident:	
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
2019 Gas Refresher Training				
February 11, 2019: (3 Operator Training)				
Traveled to Spokane, WA to conduct inspection.				
5 1				
February 12, 2019:				
Avista Fireside chat, no inspection days.				
February 13, 2019: (3 Operator Training) Met with Avista personnel at their Jack Stewart Training Center. Sat in and observed a Self-Contained Breathing Apparatus (SCBA) refresher class where employees and contractors had to don the gear and pinch off a simulated gas leak on PE and clamp a steel pipe. Fire extinguisher training consisted of simulated scenarios of four pipe fires (one stub, one service line, one meter set and one service line in a pit). Observed an Avista trainer conduct Qualifications on: PE Manual Butt Fusion, PE Mechanical Coupling, PE Mechanical Spigot and Sleeve coupling, PE Mechanical Service Tee, PE Electrofusion, PE Hydraulic Butt Fusion, Utility Locating and Odorization. February 14, 2019: (3 Operator Training)				
Traveled back to Boise, ID.				
February 15, 2019: (1 Operator Training) Typed the inspection report.				
Attached: IPUC Form 1, Inspection Summary Attendance sheet for SCBA Refresher Class Misc. Photos				
Corrective Action Required:	Λ	Yes	s No	X
Follow-up Required:	by (date):	Yes Yes	s No	Х
Close-out Letter Issued:		Yes Yes	s No	X
Inspector (Lead):	4/	MHHA	Date:	
	from the	MINV	f	eb 15 2019
Reviewer:)	Date:	